

APPENDIX C: ENTRANCE FEATURE PHOTOGRAPHS

The following photographs of entrance features provide examples from each of the condition categories, and an example of a removal.



Figure 1: Montgomery Crt & Hwy 7 (immediate replacement)




Figure 2: Bur Oak Ave & Kennedy Rd (1-5 years)

APPENDIX C: ENTRANCE FEATURE PHOTOGRAPHS

Report to: General Committee

Meeting Date: March 23, 2020



Figure 3: Woodbine Ave & Calvert Rd (6-10 years)



Figure 4: Halterwood Cir & Carlton Rd (11-15 years)

APPENDIX C: ENTRANCE FEATURE PHOTOGRAPHS

Report to: General Committee

Meeting Date: March 23, 2020



Figure 5: Roy Rainey Ave & 16th Ave (16-20 years)



Figure 6: 16 Natasha Way & Woodbine Ave (21-25 years)

APPENDIX C: ENTRANCE FEATURE PHOTOGRAPHS

Report to: General Committee

Meeting Date: March 23, 2020



Figure 7: Cornell Park Ave at 9th Line - Before

Figure 8: White's Hill Ave at 9th Line - Before

Both of these features had significant damage to their tops and were missing bricks. These two features were also blocking the sight lines when approaching 9th Line, putting pedestrians in danger. Operations removed both in 2018 and restored the sites with interlock pavers and sod.



Figure 9: Cornell Park Ave at 9th Line - After

Figure 10: White's Hill Ave at 9th Line - After