



MEMORANDUM

TO: Heritage Markham Committee

FROM: Peter Wokral, Senior Heritage Planner

DATE: April 13, 2022

SUBJECT: Site Plan Control Application

Proposed Addition to an Existing Heritage Dwelling

27 Victoria Ave., Unionville Heritage Conservation District

SPC 22 111838

Property/Building Description: Vernacular 1 ½ storey frame dwelling, c. 1871 with a modern

one storey addition

<u>Use</u>: Residence

Heritage Status: Designated under Part V of the Ontario Heritage Act and

identified as a Type 'A' building or buildings that define the

heritage character of the district.

Application/Proposal

• The owners of the property have submitted a Site Plan Control application to the City proposing to demolish the existing rear one storey modern addition in order to construct a new two storey, rear addition that would create an additional 118.1m² (1,271 ft²) of floor area.

Staff Comment

- Staff has no objection to the demolition of the existing one storey rear addition to the heritage dwelling as it has no heritage significance;
- Staff also has no concerns regarding the general form, massing, materials and architectural details of the proposed addition. See Appendix "A" for detailed comments.
- However, staff recommends that the height of the proposed addition be lowered by at least 2 ft. to make it more in scale with the existing heritage dwelling, and that volume of the second floor rooms be captured within the proposed roof structure, as per the guidelines contained in the Unionville Heritage Conservation District Plan regarding addition to heritage buildings; (See attached guidelines);
- Given that there is an existing, historic second floor door on the west facing gable of the rear tail of the heritage portion of the house, Staff supports the creation of a small balcony within the slope of the existing veranda, rather than a full balcony on new posts (as proposed), in order to limit the amount of railing visible looking east on Victoria Ave., Railings conforming to the standards of the current Ontario Building Code are not

- considered to be aesthetically compatible with historic homes, and this view of the dwelling is the most significant public view. The proposed veranda treatment would also see the removal of the historic veranda posts and replaced with a non-traditional post- this should not be supported;
- Staff also notes that a skylight has been proposed for the east slope of the tail of the heritage portion of the house. Although skylights are not considered appropriate for historic roofs or roofs visible from the public realm, staff acknowledges that this may be the preferred solution to provide some daylight to a bedroom that will have its original southward facing window(s) blocked by the proposed new addition. A flat profile skylight with glazing in a dark colour would likely be preferable to the construction of a more traditional dormer, as a new dormer would be a more significant alteration of an original roofline which would create visual clutter given the form of the proposed addition.
- A non-traditional entrance treatment has been introduced on the west elevation (new addition) with a single sidelight. However, given its location (setback) and visibility, staff had not requested revision.

Suggested Recommendation for Heritage Markham

THAT Heritage Markham has no objection from a heritage perspective to the proposed demolition of the existing one storey rear addition at 27 Victoria Avenue;

THAT Heritage Markham has no objection to the general form, massing, materials and architectural details of the proposed two storey rear addition from a heritage perspective subject to the revisions identified below;


- THAT the height of the proposed two storey addition be reduced by a minimum of 2 ft. to make the addition more in scale with the existing heritage dwelling and that the volumes of the proposed second floor rooms be contained with the roof structure;
- THAT notwithstanding the policies contained in the Unionville Heritage Conservation District Plan regarding skylights, Heritage Markham has no objection to the proposed skylight on the east facing slope of the rear tail of the heritage portion of the house provided it is flat in profile and of a glazing that closely matches the colour of the roof;
- THAT Heritage Markham does not support the proposed new veranda and balcony on the
 west side of the rear tail of the heritage portion of the house, but would support a smaller
 balcony within the existing veranda roof utilizing the existing turned porch posts;

AND THAT final review of the site plan application be referred to Heritage Section staff, provided that the revisions recommended by the Committee are incorporated into the proposal.


27 Victoria Avenue, Unionville Heritage Conservation District




27 Victoria Avenue, Unionville Heritage Conservation District




Proposed Site Plan




Proposed Elevations






Proposed Elevations





Proposed Elevations



Renderings of Proposed Addition



VICTORIA AVE - FRONT / SIDE YARD VIEW



AT VICTORIA AVE & VICTORIA LANE



FROM VICTORIA AVE

9.3 Additions to Heritage Buildings

9.3.3. design - scale

The overall design of an addition encompasses scale, proportion, articulation, composition, and detail. Only a balance of these elements results in a successful and compatible design. Drawing from the design of the existing building will make a complementary addition more easily achiev-

Although in some cases large additions are necessary, it is encouraged that additions be modest in scale compared to the existing buildings. It is often possible for large additions to be reconfigered into smaller structures and create a significant improvement to the overall presence.

Guidelines

- The design of additions should reflect the scale of the existing heritage buildings.
- An addition should not be greater in scale than the existing building.



Existing building before addition



Encouraged: modest rear addition of compatible design and scale



Appropriate: rear addition of compatible design, although scale is large



Not Appropriate: scale of addition overwhelms original house

Unionville Heritage District Plan

ĕ

APPENDIX A

Unionville Heritage Conservation District Plan Design Checklist – <u>Additions</u> to Heritage Buildings

27 Victoria Avenue

^{*} Unionville Heritage Conservation District Plan should be consulted for specific wording, if necessary

Policy (P) or guideline (G)	Review/ Comments on Specific Application
District Principles	Existing heritage resource is conserved.
3.1 Overall Goal	
To ensure the retention and conservation of the	
District's heritage resources and to guide	
change so that it contributes to and does not	
detract from the District's architectural,	
historical and contextual character.	
3.2.3 New Development Objective	
-to encourage compatible infill construction	
that will enhance the District's heritage	
character and complement to area's village-	
like, human scale of development.	
- to guide the design of new development to be	
sympathetic and compatible with the heritage	
resources and character of the District while	
providing for contemporary needs.	
4.2.2 Additions to Heritage Buildings (P)	 Although the proposed addition is
Additions should be consistent with the	compatible with the heritage dwelling
guidelines found in Section 9.3	in terms of its form, massing, materials
	and architectural detailing, the proposed
	height is out of scale with the existing
	heritage house, so it is recommended
	that the overall height be reduced by at
	least 2 ft. to improve its relationship
	with the existing house.
	 Although skylights are not supported on
	heritage roofs, the skylight proposed on
	the east facing slope of the rear tail of
	the heritage building is necessary to
	provide light to an existing bedroom
	and is a better option to adding a
	dormer provided the skylight is selected
	has a flat profile and colour similar to
	the existing roof;
	 The proposed flat roof veranda with
	balcony is not considered compatible
	with the heritage house given the
	railing requirements of the current
	Ontario Building Code. It is
	recommended that the proposed
	balcony be reduced in size and

	 incorporated within the slope of the existing veranda roof, using the existing turned porch posts in order to reduce the amount of railing required. The entrance feature on the west elevation has one sidelight which is not a typical element as per the District Plan. However, given its location, we have not recommended revision.
9.1 Streetscapes (G) Streetscape elevations should be provided for each street that will be impacted by new development. New development is not to overwhelm the streetscape but blend in/ re-enforce character	Given the proposed location of the addition and the surrounding context, a streetscape elevation is not deemed necessary to help determine the appropriateness of the proposed alterations.
9.1.X Streetscapes – Victoria Avenue (G)	Design of proposed addition reflects vernacular architecture of Victoria Avenue in terms of form, materials and simple architectural detailing.
9.3 Addition to Heritage Buildings (G)	
9.3.1 Location - attached exterior additions should be located at the rear or on an inconspicuous side - additions to be limited in size and scale in relationship to the historic building	The proposed addition is attached in the most appropriate location, but the proposed height appears out of scale with the existing heritage dwelling.
9.3.2 Design – Building Form - form of original building should be considered - attached addition should not dominate the street presence nor detract from any important historical features	The proposed addition reflects the form of the existing heritage dwelling and does not detract from any important heritage features.
9.3.3 Design – Scale - additions should reflect the scale of the existing heritage buildings - an addition should not be greater in scale than the existing building - larger additions can be reconfigured into smaller components	The proposed addition appears out of scale with the existing heritage dwelling due to its height.
9.3.4 Design- Overall - additions should be constructed to have the least possible loss of historic materials/ and character defining features are not obscured - additions should be clearly differentiated from the historic building, but be compatible in terms of mass, materials, composition and colour	The proposed addition is easily distinguished from the heritage portion of the house.

Unionville Heritage Conservation District Plan Design Checklist – <u>Alterations</u> to Heritage Buildings * Unionville Heritage Conservation District Plan should be consulted for specific wording, if necessary

Policy (P) or guideline (G)	Review/ Comments on Specific Application
District Principles (P)	The heritage resource is conserved, the
3.1 Overall Goal	proposed scale/height of the addition does
To ensure the retention and conservation of the	detract from the architectural character of the
District's heritage resources and to guide	original dwelling.
change so that it contributes to and does not	ongg.
detract from the District's architectural,	
historical and contextual character.	
instorical and contextual character.	
9.4 Alterations to Heritage Buildings (G)	
9.4.1 Roofs	The original roof form is conserved.
-conserve and maintain original roof forms (i.e.	The west veranda roof in impacted by the
roof configuration, materials, architectural	proposed deck feature.
details)	proposed deek reader.
- encourage restoration of a roof and details to	
original state- use physical and archival	
evidence. If material is unknown most	
common historic material was sawn cedar	
shingles laid with a 4 ½ to 5 ½ exposure.	
- alternative materials can be used – good	
quality composition shingle (asphalt) is	
acceptable.	
Roof Features	
· 	
- locate vents, dormers, equipment away from	
public views/ inconspicuous as possible.	The man and dealth is accorded.
- locate solar panels, skylights and satellite	The proposed skylight is acceptable
equipment on new additions; not heritage fabric.	notwithstanding the District guidelines
	provided it is flat in profile and of a colour
- retain original chimneys. Non-functioning	designed to match the colour of the roof.
chimneys can be capped/ repointed rather than	
removed.	
- ensure new chimneys are complementary in	
design to originals and building's architectural	
style.	
9.4.2 Exterior Cladding	No change is proposed to original exterior
- conserve and maintain original, external	cladding.
finishes. Repair rather than replacement. If	g.
replacement is necessary, material should	

match the original in form, style, dimensions, profile, texture and method of installation.

- only replace specific components that are deteriorated rather than the entire board or wall.
- don't apply new surfaces or coatings that alter the appearance and character or the original cladding.
- metal and synthetic sidings are not supported
- remove unsympathetic sidings (i.e. aluminium and vinyl, tile, anglestone, etc) and restore to original state using physical/ archival evidence. If unknown, use a traditional siding material appropriate to the building and commonly used in the District.

Existing Wood

- only replace when it has lost its material integrity/ ability to hold a surface coating.
- keep wood painted/ don't strip bare.

Existing Brick

- only repoint masonry when it is badly deteriorated or if water penetration is an issue. Normal for older mortar to be weathered back
- don't disturb old mortar in good condition.
- use those skilled and experienced in historic mortar if repointing is necessary
- use hand tools to cut out masonry and mortar to minimize risk of damage
- match new mortar in terms of colour, composition (such as soft lime rich variety for pre-1920), and pointing method.
- don't paint unpainted brick surfaces
- if painted, ensure that the brick is not a soft brick that was meant to be painted.
- don't seal brick surfaces with silicones or waterproof coatings as these can trap moisture. Cleaning Claddings
- always use the gentlest method
- avoid abrasive cleaning methods that strip wood of existing finishes or impact historic masonry (sandblasting, waterblasting, harsh chemical cleaners.
- test cleaning methods in an inconspicuous sample area

9.4.3 Windows and Doors

- original windows and doors to be conserved and well maintained
- if a component is deteriorated beyond repair, the component should be replicated in the same

Existing original window and door openings are retained.

material, style and proportion- not the entire unit - encourage replacement of newer windows and doors that are unsympathetic to the building. Replacements should reflect the original condition using physical/archival evidence. It original design is unknown, use a design appropriate to the building style. Openings (Altering/New) - avoid altering original door and window openings – not appropriate - if necessary, new window or doors should only be introduced on the rear or other inconspicuous elevations – Respect the size and placement of traditional openings elsewhere on the building. Shutters - conserve and maintain original shutters. Existing shutters are retained. Repair rather than replace. If replacement is needed, match the original materials, form, style, dimensions, profile, texture, method of installation. - base the introduction of shutters on the style of the building, and available physical/archival evidence. Storm Windows/Doors Existing storm windows are retained. - encourage the use of traditional ext. storm windows. Pane division should match underlying window or be simpler. - encourage the use of traditional, simple, wood screen/storm door **Thermopane Windows** - original windows in good condition should Original windows are retained not be replaced with thermopane units - if completely deteriorated original windows or newer windows require replacement and restoration in a traditional manner is not to be pursued, the use of a thermopane replacement window is an option. The thermopane windows unit to be the same size, proportion and posses the correct pane division- true divided lites with real externally perceivable muntin bars 9.4.4 Foundation - conserve and maintain original foundation No changes to existing foundation materials. Repair as opposed to replacement.

- only replace specific components that are deteriorated rather than the entire wall.

- don't apply new surfaces or coatings that alter	
the foundation's appearance and character (i.e.	
parging)	
Repair to Fieldstone	
- only undertake repointing when it is badly	
deteriorated or when water penetration is an	
issue. Don't disturb old mortar in good	
condition.	
- use those skilled and experienced in historic	
mortar if repointing is necessary	
- use hand tools to cut out mortar to minimize	
risk of damage	
- match new mortar in terms of colour,	
composition (such as soft lime rich variety for	
pre-1920), and pointing method.	
9.4.5 Architectural Details	
- conserve and maintain original architectural	Surviving heritage features are retained
details. Repair is preferred over replacement.	
- If replacement is necessary, material should	
match the original in form, style, dimensions,	
profile, texture and method of installation.	
- only replace specific deteriorated materials	
rather than the entire feature.	
- introducing specific architectural details	
should be based on the style of the building and	
any physical/ archival evidence - if shutters are used- traditional louvered wood	
variety, fit the window shape, be ½ of the width of the window, and attached at the	
· · · · · · · · · · · · · · · · · · ·	
frame. 9.4.6 Porches	The west elevation veranda is altered with the
- conserve and maintain original porches - an	introduction of an upper deck with railings, and
integral part of heritage building	the porch posts are replaced with a treatment
- if a component such as bracket, post or railing	not compatible. This should be revised.
has deteriorated, the feature should be	not compatible. This should be revised.
replicated in the same material, style or	
proportion	
- encourage the replacement of newer,	
unsympathetic porches. Use archival/physical	
evidence. If original design is unknown, use a	
design appropriate to the style of the building	
- filling in or removal of porches to be avoided	
9.4.7 Paint Colour	
- retain original exterior paint finish/colour if	
still intact. Repaint using original colours.	
- encourage researching colour used on the	
structure or used in the period of construction.	
- select colours suitable and appropriate to the	
street corours surmore und appropriate to the	

period and style of the building and compatible with surrounding heritage buildings. - don't paint unpainted barns and driving sheds - keep historically painted surfaces painted (don't strip to bare wood) - don't paint brick surfaces	
 9.4.8 Energy Conservation ensure alterations related to energy conservation measures are sensitive to the original heritage features. encourage the use of insulation (basement and attic) 	
-encourage proper maintenance such as caulking and sealing - interior or exterior storms to improve thermal efficiency.	
 9.4.9 Accessibility Considerations highest level of access for those with disabilities with the lowest level of impact on heritage features introduce barrier free access requirements so 	
that character defining spaces, features, details and finishes are preserved. 9.4.10 Landscape and Building Features	
- conserve and maintain existing features that are considered to be significant (fences, walkways, gardens, driveways, sheds, walls	
 encourage restoration of heritage gardens new parking areas should be introduced in a manner that has minimal impact on lawns, gardens, mature vegetation. 	
9.4.11 Restorationrecommend undertaking historical and architectural research to formulate a restoration plan.	
- retain as much of the original building fabric as possible when restoration occurs	

Q:\Development\Heritage\PROPERTY\VICTORIA AVE\27\2022 Site Plan Application\Site Plan Checklist against UHCD policies and guidelines.doc