



# MEMORANDUM

TO:	Heritage Markham Committee
FROM:	Peter Wokral, Senior Heritage Planner
DATE:	June 8, 2022
SUBJECT:	Site Plan Control & Variance Application 25 Victoria Ave, Unionville Heritage Conservation District Proposed Rear Addition to an Existing Heritage Dwelling SPC 22 116892 & A/065/22

<b><u>Property/Building Description</u></b> :	1-1/2 Storey Frame Heritage Dwelling constructed circa 1896
Use:	Residential
<u>Heritage Status:</u>	Designated under Part V of the Ontario Heritage Act and
	identified as a Type 'A' building or buildings that define the
	heritage character of the district.

#### **Application/Proposal**

The applicant proposes to construct a 549 ft<sup>2</sup> ( $51m^2$ ) detached garage, demolish the one storey historic rear tail of the existing heritage dwelling in order construct a 2,126 ft<sup>2</sup> (197.5m<sup>2</sup>) two storey addition, construct a new front veranda which requires the following variances to the Zoning By-law to permit:

- 1. a front yard setback of 5 feet 2 inches to the front covered porch, whereas the By-law requires 25 feet.
- 2. a maximum lot coverage of 34.5 percent, whereas the By-law permits a maximum lot coverage of 33.3 percent.
- 3. a rear concrete deck without cellar below to project 3.66 metres, whereas the By-law permits a maximum projection of 3.0 metres.
- 4. window openings at an elevation of 174.7 metres, whereas the bylaw requires an elevation of 174.8 metres.

#### **Background**

- The property is part of Lot 7 in William Eakin's plan of village lots (Plan 348), 1873.
- The house built by Delos and Jennie Harrington c.1896.
- Delos Harrington was a co-owner of the Planning Mill at that time. In 1905, the family built a new two storey brick house at 130 Main Street.

#### **Staff Comment**

- Staff does not support the proposed alteration to the existing front porch which appears to be an original heritage feature of the house based on archival photographs;
- Staff has no objection to the demolition of the historic rear tail as is located in the only logical and appropriate portion to which to attach a modern two storey addition to the existing heritage dwelling. The tail should be examined to determine any features that could be salvaged for future use;
- Staff has no objections to the requested variances, as they either reflect an existing historic condition ( the setback of the existing front porch from the front property line), are minor in nature, or have no impact from a heritage perspective;
- However, staff recommends that the architectural form of the proposed addition be revised to better reflect the forms and simple massing of the existing heritage house;
- The proposed addition would appear to negatively impact a large Norway Maple tree located on the property to the east, and the proposed detached garage requires the removal of trees located at the rear of the property;
- Staff recommends that the submitted drawings be annotated to identify materials, heritage features to be retained and new materials, and that elevation drawings for the garage be submitted;
- Staff also recommends that underlying historic siding of the heritage house be exposed, and that two over two single hung windows be installed in the heritage portion of the house to replace any existing modern replacement windows (See Attachment 4- Design Checklist for Alterations and Additions to Heritage Buildings)

#### Suggested Recommendation for Heritage Markham

THAT Heritage Markham does not support the proposed front veranda and recommends that the existing historic front porch be retained in its current form;

THAT Heritage Markham has no objection to the requested variances from a heritage perspective;

THAT the proposed addition be revised to better reflect the architectural form and simple massing of the existing heritage dwelling;

THAT the drawings be annotated to identify materials, heritage features to be retained and new materials, and garage drawings be submitted;

THAT the underlying historic siding of the heritage dwelling be revealed and restored, and that any modern replacement window be replaced with new historically authentic windows.

AND THAT the submission be revised and return to Heritage Markham Committee for review.

**Attachment 1- Property Location** 


Attachment 2-Photograph of Existing Heritage Dwelling

**Attachment 3-Proposed Site Plan & Elevations** 

**Attachment 4- Design Checklist for Alterations and Additions to Heritage Buildings** 


Attachment 5 – Design Checklist for New Construction - Garage

# **Attachment 1- Property Location**




25 Victoria Avenue, Unionville Heritage Conservation District

# **Attachment 2 - Photographs of Existing Heritage Dwelling**



25 Victoria Avenue, Unionville Heritage Conservation District




Addition will be visible primarily on west elevation from the public realm



Existing decorative porch (north elevation)

## **Attachment 3 - Proposed Site Plan & Elevations** Proposed Site Plan



# Proposed Elevations



Front (street facing elevation)





# Attachment4- Design Checklist for Alterations and Additions to Heritage Buildings

#### Unionville Heritage Conservation District Plan Design Checklist – <u>Additions</u> to Heritage Buildings

\* Unionville Heritage Conservation District Plan should be consulted for specific wording, if necessary

Policy (P) or guideline (G)	<b>Review/ Comments on Specific Application</b>
District Principles	
3.1 Overall Goal	
To ensure the retention and conservation of the	• The applicant proposes to retain the two
District's heritage resources and to guide	storey portion of the existing heritage
change so that it contributes to and does not	dwelling, but proposes to demolish an
detract from the District's architectural,	existing one storey tail that appears to
historical and contextual character.	be a historic kitchen tail, typically
3.2.3 New Development Objective	constructed on a substandard
-to encourage compatible infill construction	foundation with no basement.
that will enhance the District's heritage	• There may be features that could be
character and complement to area's village-	salvaged for use on the existing house.
like, human scale of development.	6
- to guide the design of new development to be	
sympathetic and compatible with the heritage	
resources and character of the District while	
providing for contemporary needs.	
<b>4.2.2 Additions to Heritage Buildings</b> (P)	See below
Additions should be consistent with the	
guidelines found in Section 9.3	
9.1 Streetscapes (G)	
Streetscape elevations should be provided for	
each street that will be impacted by new	• Due to the proposed location of the
development.	addition, it should not overwhelm the
New development is not to overwhelm the	existing streetscape despite being taller
streetscape but blend in/ re-enforce character	than the existing heritage dwelling.
9.3 Addition to Heritage Buildings (G)	
9.3.1 Location	
- attached exterior additions should be located	• The proposed addition is appropriately
at the rear or on an inconspicuous side	located at the rear of the existing
- additions to be limited in size and scale in	heritage building but this also
relationship to the historic building	necessitates the removal of the existing
	one storey historic tail in order to
	provide connection between the
	existing second floor of the heritage
	house and the second floor of the
	proposed addition.
	• Small connection between heritage
	house and new addition is lower than

Policy (P) or guideline (G)	<b>Review/ Comments on Specific Application</b>
	heritage roof
<ul> <li>9.3.2 Design – Building Form <ul> <li>form of original building should be</li> <li>considered</li> <li>attached addition should not dominate the</li> <li>street presence nor detract from any important</li> <li>historical features</li> </ul> </li> </ul>	<ul> <li>The proposed addition does not dominate the street presence or detract from any important historical features, but it does not reflect the form of the existing heritage building in terms of its complexity or roof types;</li> <li>The proposed addition does not detract from any important historic features.</li> </ul>
<ul> <li>9.3.3 Design – Scale</li> <li>additions should reflect the scale of the existing heritage buildings</li> <li>an addition should not be greater in scale than the existing building</li> <li>larger additions can be reconfigured into smaller components</li> </ul>	• A larger addition
<b>9.3.4 Design- Overall</b> - additions should be constructed to have the least possible loss of historic materials/ and character defining features are not obscured - additions should be clearly differentiated from the historic building, but be compatible in terms of mass, materials, composition and colour	<ul> <li>Although the proposed addition proposes the loss of the existing historic one storey rear kitchen tail, this represents the only logical and appropriate place to construct a new addition to the existing dwelling.</li> <li>The proposed addition is clearly differentiated from the existing historic building, but is not compatible in terms of its form and massing;</li> <li>More subtle means of differentiating the addition from the existing historic dwelling are recommended, such as a change in the exterior cladding from old to new.</li> </ul>

#### Unionville Heritage Conservation District Plan Design Checklist – Alterations to Heritage Buildings

**Design Checklist** – <u>Alterations</u> to Heritage Buildings \* Unionville Heritage Conservation District Plan should be consulted for specific wording, if necessary

Policy (P) or guideline (G)	<b>Review/ Comments on Specific Application</b>
<b>District Principles (P)</b> <b>3.1 Overall Goal</b> To ensure the retention and conservation of the District's heritage resources and to guide change so that it contributes to and does not detract from the District's architectural, historical and contextual character.	• The 1 ½ storey portion of the existing heritage house is to be conserved, but the existing one storey rear tail is proposed to be demolished to allow for the proposed two storey addition;
9.4 Alterations to Heritage Buildings (G)	
<b>9.4.1 Roofs</b> -conserve and maintain original roof forms (i.e.	• The applicant proposes to change the distinctive historic roof of the front

Policy (P) or guideline (G)	<b>Review/ Comments on Specific Application</b>
<ul> <li>roof configuration, materials, architectural details)</li> <li>encourage restoration of a roof and details to original state- use physical and archival evidence. If material is unknown most common historic material was sawn cedar shingles laid with a 4 ½ to 5 ½ exposure.</li> <li>alternative materials can be used – good quality composition shingle (asphalt) is acceptable.</li> <li>Roof Features</li> </ul>	porch to create a full width front veranda of a standard, schematic non- historic design. Not supported.
<ul> <li>locate vents, dormers, equipment away from public views/ inconspicuous as possible.</li> <li>locate solar panels, skylights and satellite equipment on new additions; not heritage fabric.</li> <li>retain original chimneys. Non-functioning chimneys can be capped/ repointed rather than removed.</li> <li>ensure new chimneys are complementary in design to originals and building's architectural style.</li> </ul>	• The applicant proposes to remove a non-functioning modern brick chimney located on the west elevation of the historic portion of the house. Supported
<ul> <li>9.4.2 Exterior Cladding <ul> <li>conserve and maintain original, external finishes. Repair rather than replacement. If replacement is necessary, material should match the original in form, style, dimensions, profile, texture and method of installation.</li> <li>only replace specific components that are deteriorated rather than the entire board or wall.</li> <li>don't apply new surfaces or coatings that alter the appearance and character or the original cladding.</li> <li>metal and synthetic sidings are not supported</li> <li>remove unsympathetic sidings (i.e. aluminium and vinyl, tile, anglestone, etc) and restore to original state using physical/ archival evidence. If unknown, use a traditional siding material appropriate to the building and commonly used in the District.</li> </ul> Existing Wood <ul> <li>only replace when it has lost its material integrity/ ability to hold a surface coating.</li> <li>keep wood painted/ don't strip bare.</li> </ul></li></ul>	<ul> <li>The drawings do not indicate whether the exterior cladding of the heritage house is new, existing or the original historic cladding;</li> <li>The drawings should be revised to indicate that the underlying historic cladding is to be uncovered, and restored.</li> </ul>

Policy (P) or guideline (G)	<b>Review/</b> Comments on Specific Application
style, dimensions, profile, texture, method of	
installation.	
- base the introduction of shutters on the style	
of the building, and available physical/archival	
evidence.	
Storm Windows/Doors	
- encourage the use of traditional ext. storm	
windows. Pane division should match	
underlying window or be simpler.	
- encourage the use of traditional, simple, wood	
screen/storm door	
Thermopane Windows	
- original windows in good condition should	
not be replaced with thermopane units	
- if completely deteriorated original windows	
or newer windows require replacement and	
restoration in a traditional manner is not to be	
pursued, the use of a thermopane replacement	
window is an option. The thermopane	
windows unit to be the same size, proportion	
and posses the correct pane division- true	
divided lites with real externally perceivable	
muntin bars	
9.4.4 Foundation	
- conserve and maintain original foundation	• It is assumed that the existing granite
materials. Repair as opposed to replacement.	fieldstone foundation is to be retained,
- only replace specific components that are	as drawings do not indicate the
deteriorated rather than the entire wall.	relocation of the existing house or
- don't apply new surfaces or coatings that alter	construction of a new basement.
the foundation's appearance and character (i.e.	
parging)	
<b>Repair to Fieldstone</b>	
- only undertake repointing when it is badly	
deteriorated or when water penetration is an	
issue. Don't disturb old mortar in good	
condition.	
- use those skilled and experienced in historic	
mortar if repointing is necessary	
- use hand tools to cut out mortar to minimize	
risk of damage	
- match new mortar in terms of colour,	
composition (such as soft lime rich variety for	
pre-1920), and pointing method.	
9.4.5 Architectural Details	
- conserve and maintain original architectural	• The front elevation proposes the
details. Repair is preferred over replacement.	removal of the original historic front

Policy (P) or guideline (G)	<b>Review/ Comments on Specific Application</b>
<ul> <li>If replacement is necessary, material should match the original in form, style, dimensions, profile, texture and method of installation.</li> <li>only replace specific deteriorated materials rather than the entire feature.</li> <li>introducing specific architectural details should be based on the style of the building and any physical/ archival evidence</li> <li>if shutters are used- traditional louvered wood variety, fit the window, and attached at the frame.</li> </ul>	<ul> <li>porch roof. Not supported</li> <li>The elevations do not indicate whether the shutters are existing modern inappropriate shutters or historically authentic wooden louvred shutters.</li> <li>Shutter are not shown on side elevations</li> </ul>
<ul> <li>9.4.6 Porches <ul> <li>conserve and maintain original porches - an integral part of heritage building</li> <li>if a component such as bracket, post or railing has deteriorated, the feature should be replicated in the same material, style or proportion</li> <li>encourage the replacement of newer, unsympathetic porches. Use archival/physical evidence. If original design is unknown, use a design appropriate to the style of the building</li> <li>filling in or removal of porches to be avoided</li> </ul> </li> <li>9.4.7 Paint Colour <ul> <li>retain original exterior paint finish/colour if still intact. Repaint using original colours.</li> <li>encourage researching colour used on the structure or used in the period of construction.</li> <li>select colours suitable and appropriate to the period and style of the buildings.</li> <li>don't paint unpainted barns and driving sheds</li> <li>keep historically painted surfaces painted (don't strip to bare wood)</li> <li>don't paint brick surfaces</li> </ul> </li> </ul>	<ul> <li>The proposed front veranda does not conserve the original porch roof and is therefore not supported.</li> <li>Exterior colours are not specified in elevations.</li> <li>Appropriate heritage colour will need to be confirmed</li> </ul>
<ul> <li>9.4.8 Energy Conservation <ul> <li>ensure alterations related to energy</li> <li>conservation measures are sensitive to the</li> <li>original heritage features.</li> <li>encourage the use of insulation (basement and attic)</li> <li>encourage proper maintenance such as</li> <li>caulking and sealing</li> </ul> </li> </ul>	

Policy (P) or guideline (G)	<b>Review/ Comments on Specific Application</b>
- interior or exterior storms to improve thermal	
efficiency.	
9.4.9 Accessibility Considerations	
- highest level of access for those with	
disabilities with the lowest level of impact on	
heritage features	
- introduce barrier free access requirements so	
that character defining spaces, features, details	
and finishes are preserved.	
9.4.10 Landscape and Building Features	• Assume front yard fence is to be
- conserve and maintain existing features that	retained
are considered to be significant (fences,	
walkways, gardens, driveways, sheds, walls	
- encourage restoration of heritage gardens	
- new parking areas should be introduced in a	
manner that has minimal impact on lawns,	
gardens, mature vegetation.	
9.4.11 Restoration	Original historic underling wood siding
- recommend undertaking historical and	should be exposed and restored if
architectural research to formulate a restoration	possible, or accurately replicated if it is
plan.	not feasible to restore.
- retain as much of the original building fabric	
as possible when restoration occurs	

## **Attachment 5 – Design Checklist for New Construction - Garage**

### **Unionville Heritage Conservation District** New Construction - Garage

\* Unionville Heritage Conservation District Plan should be consulted for specific wording, if necessary.

Address: \_\_25 Victoria Ave\_\_\_\_\_

Plan Policy or Guideline	Specific Application Comment
4.3 New Buildings	• New detached garage is setback on
- A successful new building should not stand	property
out or challenge the character of the street $-$ it	
should blend in and re-enforce the heritage	
character	
4.3.1 Design Approach	
- New buildings should complement the	
immediate physical context and streetscape by:	
- being of generally the same height,	
width and orientation of adjacent	
buildings;	
- being of similar setback;	
- being of like materials and colours,	
and,	
- using similarly proportioned windows,	
door and roof shapes.	
9.1.1 Streetscapes – Overview	• New detached garage is setback on
- New developments should not overwhelm the	property
streetscape but rather blend in and reinforce the	
heritage character.	
9.2.1 Style	Drawings not provided
The style of new construction should be	
sensitive to its surroundings. It need not	
imitate exactly the older styles of existing local	
buildings but should respond to the spirit of its	
surroundings.	
• Design a product of its own time but	
reflects one of the District's historic	
styles;	
• Consistent approach to design elements	
within the chosen style;	
• Simplicity is the overwhelming local	
architectural character;	

Plan Policy or Guideline	Specific Application Comment
• The predominant historical style on the	
street should be considered when	
selecting a style for new houses.	
9.2.2 Overall Scale	
- While new construction may vary in scale	
from the surrounding development, it should fit	
in with existing streetscape in terms of rhythm,	
alignment and spacing.	
- The scale of larger buildings can be reduced	
by breaking up the façade and overall massing	
into elements that reflect adjacent building	
forms.	
9.2.4 Building Form: Height	
- Compatible with traditional height pattern in	
the District (1 $\frac{1}{2}$ - 2 storeys), regard for the	
heights of adjoining buildings.	
- Submission of scaled streetscape with	
adjoining structures, two on corner lots.	
9.2.5 Location and Setbacks	• Detached garage complies with setback
- Accessory buildings should not form part of	guideline
the front façade, but be located towards the rear	
of the property.	
9.2.6.1 Roofs – Historic Types	
- Roof types for new buildings should be	
compatible with historic roof forms in the area	
and the selected building style.	
9.2.6.6 & 9.2.6.7 Dormers	
- Dormers in new construction should be	
consistent with the style of the building and	
follow traditional scale and proportions.	
9.2.7.1 Windows	
- Windows in new construction should reflect	
the historic windows styles in the District, and	
be consistent with the architectural style of the building.	
9.2.7.4 Windows – Muntin Bars	
- Where divided windows are proposed, they	
should either be true divided panes or exterior	
adhered muntin bars.	
- The pane divisions should be compatible with	
the style of the house.	
9.2.7.8 Window and Door Placement	
- On facades visible from the street, windows	
should maintain historic proportions and	
placement patterns.	
- A door should be visible on the front façade	
and placed in a traditional manner.	

Plan Policy or Guideline	Specific Application Comment
9.2.7.10 Doors – Historic Styles	
- The style of door should be consistent with	
the architectural style of the house and reflect	
local historic styles.	
- Wood doors are preferred.	
9.2.9 Cladding Materials	
- Materials used in new construction should be	
compatible with the historic materials used in	
the District.	
- Avoid modern materials that do not reflect	
the historical architecture of the District, such	
as vinyl, aluminum, stone and smooth stucco.	
9.2.13.1 & 9.2.13.2 Garages	Garage complies with guidelines
- Garages should be set back from the street	
and preferably separate from the building face.	
- Garages should be located toward the rear or	
at the side towards the rear of a building.	
- Detached garages are encouraged.	