


Existing Parking Condition around the Temple / Mosque near the intersection of Proctor Avenue and Bayview Avenue



↕ Existing No Parking prohibition

▲ Permitted parking
 | Capacity 50 cars
 | (Within 5 min walking
 ▼ distance of Temple /Mosque)



Attachment A


Existing Parking Condition at the Intersection of Proctor Avenue and Bayview Avenue

Engineering Dept.

October 2005





 Proposed Parking Restriction

Attachment B

Proposed Parking Restriction at the Intersection of Proctor Avenue and Bayview Avenue

Engineering Dept.

October 2005

